


## Safety Newsflash No 12-10



A Scaffolder attempting to attach his safety inertia reel to the small lanyard on the back of his harness, accidentally attached it to the rubber ID TAG, which was sent along with the W @ H equipment from onshore. It was noticed by another member of his team straight away they then reported it immediately.

### Actions:

- **Remove these ID TAGS now!**
- **Ensure YOU as a TEAM perform buddy checks on each other when using any W @ H equipment, this is a vital role you play in ensuring your teams safety.**

*Managing Director*

Date

24/05/10

TMS/10/F/02  
Rev 05